

REPORT ON CAUSES AND REMEDIAL MEASURES
WAIOMAO SLIDE, HONOLULU

by

GREGG M. SINCLAIR
UNIVERSITY OF HAWAII

Ralph B. Peck
December 1959

INTRODUCTION

This report contains a brief history of the sliding movements in the vicinity of Waiomao Homestead Road in the Palolo Valley, Honolulu. It also includes a summary of the results of the observations made in connection with the movements, a discussion of the causes, and recommendations concerning remedial measures.

HISTORY

In the latter part of 1952 a subdivision was completed on the south side of the Palolo Valley on a slope consisting in part of waste material from an old basalt quarry located higher on the hillside (Fig. 1). The subdivision consists of three streets, running parallel to the valley, named from top to bottom Kuahea Street, Waiomao Road, and Kipona Place. The elevation of Kuahea Street is approximately 440 ft above sea level and that of Kipona Place about 340 ft. The horizontal distance between the center lines of the two streets is about 460 ft. Therefore, the average slope is approximately 4.6 horizontal to 1 vertical, a relatively flat gradient.

It is reported that signs of trouble were noticed in the area as early as March 1954. By November, after heavy rainfall,^{March 57}_{Nov 57} movement became more apparent. In February 1955 it was necessary to disconnect an 8-in. water main in Kuahea Street and to relocate it in order to prevent further disruption of the water

DeS91 2.
1/2/54
closed
circles

system. From this time there is a record of continuing movements leading to difficulties with the utilities, the streets and the residences in the area.

Early in 1957 plans were prepared for a system of drainage to divert water entering the area from the basin formed by the old quarry. On 25 September of that year a program of detailed observations of horizontal and vertical movement was established. An unusually intense rain on 5 March 1958, during the time that the drainage system was being constructed, led to a marked acceleration of the movements.

In February 1958, the writer was invited by Mr. Yoshio Kunimoto, Chief Engineer of the City and County of Honolulu, to undertake a study of the slide area. A summary of available information was furnished and the writer made a field inspection of conditions during the period June 27-July 3, 1959. Following the writer's visit, the measurements of surface movements were supplemented by the installation of two tiltmeters in August 1958, for the purpose of ascertaining the location of the surface along which the sliding movements were taking place. Furthermore, during the summer and fall of 1958 several piezometers were established to determine the position of the water table in various parts of the slide.

The results of the studies suggested that the slide area is underlain by extremely pervious basalt into which the water trapped in the slide might readily be discharged by means of vertical drains. In accordance with this indication, three large-diameter drains were established along Waiomao Road to

determine whether such drainage would be effective. Continued observations indicated that the desired results were not obtained. Moreover, it has become increasingly apparent that, although the slide is caused by water trapped in the sliding mass, adequate drainage cannot be accomplished by such simple and inexpensive means.

SUBSURFACE CONDITIONS

A key plan of the slide area is shown in Fig. 2. At the location of each of the piezometers shown in this figure, as well as at the location of the drains and tiltmeters, information was obtained by test boring techniques regarding the character of the soils. Drilling through the materials was found to be difficult, and sampling almost impossible. The difficulties were a consequence of the presence of large numbers of rock fragments, some of considerable size. The materials encountered in the borings and disclosed by the samples are generally described as clay with boulders. Inspection of exposures in the locality combined with a study of the boring logs indicates that the material involved in the slide and adjacent to it consists of a mixture of basalt talus from the steep sides of the valley, weathered basalt of the consistency of clay, and some materials of intermediate sizes. At least the upper part of the slide probably consists of fill discarded from the quarry. However, this fill appears to consist essentially of the same constituents as those present in the weathered natural soils and it is not possible on the basis of the borings to determine a line of demarkation between the debris wasted from the quarry and the

natural mixture of talus and weathered rock. The basalt bedrock appears to be encountered at a depth of about 140 ft below the ground surface at Walomao Road.

The heterogeneous character of the materials precludes the possibility of laboratory analyses to determine their strength and other physical characteristics. However, as will be shown subsequently, such information is not necessary for an understanding of the slide because the field observations provide adequate information upon which to judge the nature of the movements.

DIMENSIONS OF SLIDING MASS

The outline of the sliding area is shown in plan in Fig. 2. Three cross sections through the slide showing conditions at approximately Stas. 10+40, 9+30, and 8+50 (Walomao Road stationing) are shown in Fig. 3. In these sections the position of the surface of sliding is indicated.

The location of the surface of sliding has been determined on the basis of observations of the position of the escarpment at the upper end of the slide, of the bulge at the lower end of the slide, and by the results of the tiltmeter observations. In addition to these primary data, supplementary information has been obtained by noting elevations at which various piezometers became bent to the extent that sounding devices could not be lowered in them. The data establish that the maximum depth of the slide is roughly 60 ft below the surface at Walomao Road. Thus, the slide would be classified as relatively deep. It is significant that the surface of sliding is located within the

mass of clay and rock fragments and does not extend to bedrock. Whether or not the surface of sliding coincides with the old ground surface that existed prior to the accumulation of the quarry waste is not known, but does not appear to be a matter of significance.

The tiltmeter observations proved invaluable in establishing the position of the surface of sliding and the nature of the movements. The devices were installed by Mr. Stanley D. Wilson and the preliminary results are contained in a report by Shannon & Wilson dated August 25, 1958. Subsequent observations were made by the City. All the observations indicate without any doubt that the movement is concentrated along a rather thin zone of intense shearing deformations not more than 5 to 10 ft in thickness, and that the distortions in the mass of soil above the zone of sliding, at least in the central part of the slide, are negligible. The relatively small distortions associated with the motion, except near the boundaries of the slide, account for the fact that the houses are in many instances still habitable, although the total movement has been several feet.

RATE OF MOVEMENT

Vertical and horizontal displacements have been measured periodically since 25 September 1957 at several cross sections on each of the three streets in the subdivision. The results are contained in drawings prepared by the City. They are summarized in the sketch, Fig. 4, for the period between April and June 1958. The sketch demonstrates that the movement at Kuahaea Street is largely downward with a horizontal component smaller than the vertical component. At the center line of Waiomao Road

the movement is almost exclusively horizontal. At the bottom of the slide at Kipona Place, the movement is primarily horizontal but with a substantial upward component. These motions are compatible with the shape of the surface of sliding indicated in Fig. 3.

More detailed information concerning the rates of motion is contained in Fig. 5 which shows a detailed plot of the horizontal movement of a point at Sta. 8+56 on Walomao Road. The horizontal movement of this point may be regarded as the most sensitive indicator of the activity of the slide. In connection with this figure, it may be noted that the total movement in roughly a two-year period beginning in September 1957 is on the order of six feet. The movement has not increased at a constant rate but has progressed in rapid steps, separated by periods of somewhat slower motion.

To permit a closer examination of the character of the movement, the rate of horizontal movement has been plotted on the same diagram. This rate is taken as the slope of the curve representing the horizontal movement. It may be noted that the rate of movement has generally been fairly small, on the order of .01 to .02 ft per day, except for certain brief periods when substantially greater rates developed.

The same diagram contains a plot of the rainfall indicated by the gage on Wilhelmina Rise, above the quarry, Fig. 1. It is apparent that the peaks of the rate of movement occur at the same time as the maximum total rainfall. That is, there is an extremely close correlation between the rate of movement and

the rate of rainfall as measured by the total rainfall in successive 10-day periods.

PIEZOMETRIC LEVELS

Most of the piezometers established in the slide area consist of pipes perforated throughout their length. The water levels in the pipes should, therefore, represent the elevations of the free water surface corresponding to the most pervious zones of material traversed by the piezometers. The variations in piezometric elevation at the locations are shown as a function of time in Figs. 6 and 7. Some of the piezometers appear to be relatively stable and virtually unaffected by periods of intense rainfall. Others are quite sensitive to rainfall and show abrupt rises in water level in a rainy period followed by relatively rapid reduction to a more normal value. The usual water levels displayed by the piezometers in recent months are shown in Fig. 3 on the three cross sections previously discussed. If a piezometer indicates rather frequently higher or lower values than the usual values, the extreme indications are shown by open triangles whereas the solid triangles represent the usual positions.

It may be observed that, as a very rough statement, the water levels in the upper and the lower parts of the slide are relatively low compared to the position of the surface of sliding, but those near Waiomao Road are rather high. The erratic distribution of piezometric levels signifies the presence of pockets of relatively pervious material separated from other pockets by virtually impervious barriers.

Of particular interest are the water levels observed in

the deep holes made for the tiltmeters. These holes extended into the bedrock and the tiltmeter casings were not perforated. However, the casings were open at their lower ends. The casings would not hold water and remained dry for a considerable period of time after their installation, indicating that the free water surface in the basalt layers was well below their bottoms. However, as soon as the casings deformed to the extent that they were sheared off at the surface of sliding, the water levels rose to values corresponding to those of nearby piezometers.

In October and November 1958, three drains were placed along Walomao Road. These consisted of vertical pipes, one having a diameter of 12 inches and the other two having diameters of 10 inches. The pipes, perforated with slots throughout their length, extended through the slide into the underlying basalt. They were subsequently filled with pea gravel in which was located a smaller pipe, also with perforations, for the purpose of permitting observations of the water level. The water levels in these pipes were consistently at a depth of 70 to 90 ft below the surface of the slide. Thus, the drains were capable of discharging water into the underlying basalt. Yet, nearby piezometers located in the sliding mass did not react to the presence of the drains. Therefore, it was apparent that the drains were not serving the intended purpose. Because of the possibility that the casings might be inhibiting the flow of water from the slide material into the drains, these casings were pulled in August 1959. Nevertheless the drains, which then consisted of columns of gravel, did not have an influence sufficiently great to be reflected in the readings of any of the adjacent piezometers.

INTERPRETATION OF DATA

All the information in the preceding sections suggests that the sliding mass consists of a very heterogenous deposit of clay and rock fragments locally quite pervious. The pervious zones, however, appear to be separated by relatively impervious boundaries. For this reason each pervious zone is likely to collect water which rises to a level corresponding to the boundary conditions of the zone, but unrelated to the water levels in other nearby zones. Some of the pervious zones are apparently drained but in many the water table is relatively high.

It is also indicated that the surface of sliding consists of a "smear zone" that serves as a very impervious barrier to the flow of water from overlying pockets into the underlying materials. In spite of the fact that the entire sliding mass is underlain by pervious basalt with a low water table, so that it might be regarded as perfectly drained, the slide itself is not drained because of the ability of the smear zone to hold substantial quantities of water and because of the ability of local pervious zones to trap water at even higher levels. The extremely random nature of the pervious zones and the impermeability of the boundaries between some of them is indicated by the lack of relationship between water levels in piezometers located close to each other and by the lack of reaction of the piezometers to the large-diameter drains located nearby.

There is no doubt, according to Fig. 5, of the close correlation between rate of rainfall and rate of movement.

Hence, there can be no doubt that the basic causes of the slide are the reduction in effective frictional resistance of the soil near the surface of sliding as a consequence of high pore pressures, and the increase in the weight of the soil above the surface of sliding as a consequence of the trapped water. These two factors combine to reduce the factor of safety against sliding and to cause accelerations of the motions. Therefore, it may be inferred that lowering the water table in those pockets with excessively high piezometric levels should be the most direct means of stabilizing the slide.

A study of Fig. 5 indicates that during September and October 1957, when the rainfall was very low, the rate of horizontal movement was also very low. This period was preceded by several months of extremely low rainfall. Comparable periods of low rainfall appeared to have occurred about 400 days after the start of the observations and again about 600 days after the start of the observations. The rates of horizontal movement corresponding to both of these periods are also extremely small. However, during all other times in the 800 day period embraced by the diagram, the somewhat greater amount of rainfall produced appreciably greater movements. To stabilize the slide it will be necessary to reduce the water pressures to values somewhat lower than those corresponding to the three dry periods indicated in the figure. In general, this must be accomplished either by preventing water from entering the slide area, by draining water that does enter the slide area, or by a combination of the two procedures.

The data also suggest that the hillside area upon which the subdivision was later established may have been creeping downward for a period of many years. Such movements, without objects to provide a frame of reference, might easily have gone undetected. It seems not at all unlikely that construction of the subdivision merely provided physical objects whose relative positions could easily be observed and that the sliding movements became apparent only after the subdivision had been laid out. There does not appear to be any reason to suppose that the start of the slide coincided with or was caused by the work associated with the subdivision. The minor amounts of grading seem unlikely to have caused large enough changes in weight to initiate movement of a previously stable mass.

After the establishment of the subdivision, however, the existence of water and sewer lines which could be broken by the movements provided a means for the ingress of more water than may have been able to get into the slide due to natural causes alone. With increasing movement and frequency of breakage of water and sewer lines, the rate of movement may well have had a tendency to accelerate. The exceptionally heavy rainfall of March 1958 was also a factor contributing to rapid acceleration of the slide and thus caused marked damage to utilities. Therefore, it is not surprising that movements accelerated for a considerable period after this rainfall. A somewhat similar occurrence seems to have taken place at a time of approximately 100 days after the initiation of observations when a somewhat less intense, but nevertheless important, rainy period occurred.

Theoretical studies not included in this report also lead to the conclusion that a lowering of the water table would be beneficial. The calculations indicate that, if the factor of safety of the slide is considered to be 1.0 when the water level is 5 ft below the general ground surface, the factor of safety will be raised to about 1.2 if the water table is 15 ft below the surface and to about 1.4 if the water table is 25 ft below the surface. Hence, the results of the theoretical calculations substantiate the conclusions derived from the field observations to the effect that a moderate lowering of the water levels within the slide will have substantial beneficial toward stabilizing the mass.

DESIRABLE REMEDIAL MEASURES

The stability of a slide may be improved by one or both of two procedures: by decreasing the forces tending to produce the slide or by increasing the resistance of the sliding material.

In the present instance the expedient of reducing the driving forces by unloading the upper part of the slide is not feasible because the entire area is occupied by residences. The only other means available for reducing the driving forces is the reduction of the unit weight of the sliding material. This can be accomplished to at least a small extent by a reduction in the water content; that is, by drainage.

Increasing the resistance of the sliding material has in practice been accomplished by several means. One of these consists of excavating to the surface of sliding along narrow benches extending from bottom to top of the slide and filling

ditches with resistant material, such as masonry ribs. Other consists of driving piles or inserting piers extending from the sliding mass into the stable soil beneath. Procedures of this type are not suitable in connection with the Walomao slide because of the extreme depth to the surface of sliding. Driving of piles, for example, has proven useful only in shallow slides. In deep slides the piles merely bend and ultimately experience failure along the surface of sliding.

In principle, strengthening of the sliding material may also be accomplished by injecting material such as cement grout into the interstices of the soil near the surface of sliding, by injection of suitable chemicals, or by electro-osmosis. The injection procedures are likely to be expensive and the results are uncertain. Since it is believed that the depth of sliding is at least several feet thick in the Walomao slide and is quite impermeable, it is doubtful if any injected material could be made to penetrate that part of the mass of soil in which the sliding actually takes place. Electro-osmosis would very probably be successful but could only be undertaken after exhaustive and expensive tests and would unquestionably be extremely expensive.

The final procedure for increasing the resistance of the sliding material is the reduction of the water pressure along the surface of sliding. The shearing resistance of the material, so far as the soil has frictional characteristics, depends upon the pressures exerted from grain to grain. These pressures are reduced by whatever water pressure exists in the voids. Hence,

lowering the water pressure constitutes a direct means of increasing the stability of the mass.

The preceding summary of remedial measures strongly indicates that the only practicable means for stabilizing the Natomas slide is some form of drainage. The drainage will serve to reduce the driving forces and to increase the resisting forces. Therefore, from a technical and economic point of view the only question is the manner by which the drainage can best be accomplished.

An important consideration in the selection of a drainage system is the fact that movements of the sliding mass are likely to continue during the installation of the drains and possibly for a short time thereafter. Hence, any system of drains that would be rendered inoperative as a result of the movements cannot be considered satisfactory.

A second consideration is that the drainage system should preferably discharge the water by gravity rather than by reliance on continued pumping. The necessity for continued maintenance of a pumping system, while not an absolute reason for rejection of a given system, is at least a considerable drawback.

Even in the earliest studies made of the slide, drainage by horizontal auger holes, known as hydranger holes, was given serious consideration. Such drains have been used with exceptionally good success in the stabilization of many hillside slope failures. The drains are installed by boring almost horizontally into the face of the hillside by means of power drills or augers which make holes that are subsequently filled with gravel and serve as drains. They have the advantage that

in their long horizontal extent they are relatively likely to intercept pockets of water. Furthermore, whatever water they tap can drain freely from the face of the auger hole and can be removed by ordinary ditches or pipe lines on the surface. At an early stage of the investigation the writer considered the horizontal drains to be an excellent possibility for stabilization and proposed a tentative layout of such drains. Subsequent studies have suggested, however, that the drains are not likely to be as successful as at other locations.

The installation of hydrauger holes is particularly difficult if many obstructions, such as boulders, are present. Moreover, to be effective beneath a slope as flat as that at the Waiomao slide, the drains must be at least 100 and preferably 150 ft long. Experience at this slide with the installation of piezometer holes and of vertical drains, as well as general knowledge of the character of the soil conditions, suggest very strongly that the probabilities are very low of installing any appreciable number of horizontal drains of the required length.

The necessity for drains of considerable length is shown in the cross section, Fig. 8. Since the drains must be installed at a slightly upward angle, it is apparent that the ends of drains even as long as 100 ft will not be located at great depth below the ground surface and will hardly be able to lower the water table to a depth of more than 10 or 15 ft below the present surface. In particular, the relatively flat topography of the slide near Waiomao Road itself indicates that horizontal

Drains cannot lower the water table effectively to a point much below the present water table in many of the piezometers. In the upper and lower portions of the slide near Kusha Street and Kipona Place the water tables already appear to be lower than the level that could effectively be reached by horizontal drains.

In several instances, reasoning of the type outlined above has indicated that horizontal drains would not be effective in stabilizing a slide, but the actual use of such drains has demonstrated greater efficiency than anticipated. This possibility cannot be discounted at the Walomao slide. However, it is considered that the installation of the drains is sufficiently unlikely to be successful that it should not be attempted unless no more promising solution appears feasible.

The use of vertical drainage wells under ordinary circumstances is not attractive in stabilizing a large slide because of the necessity of raising the water to the ground surface before discharging it. As a consequence, the drains must consist of relatively shallow installations such as well points interconnected by header pipes and permanently pumped, or by large-diameter drainage wells each containing its own deep-well pump. However, at the Walomao slide the presence of the pervious basalt with a low water table suggested the possibility that vertical drains could pass through the upper material and collect water, whereupon the water could be discharged by gravity into the pervious basalt beneath. As mentioned previously this procedure appeared sufficiently attractive to

grant a full-scale test by means of three drainage wells. It appeared that the ability of the wells to discharge water was entirely satisfactory, but that none of the three wells passed through a pervious zone large enough to have an influence on the water pressures in any substantial volume of sliding material.

It is not impossible that even one more vertical well might have the good fortune to encounter very pervious pockets that would effectively drain large zones of the slide. However, the pervious pockets in the slide are of appreciable size, it is surprising that the three wells did not encounter enough clefts to produce noticeable drainage. That is, the test wells indicated a low probability of encountering pervious clefts with individual vertical drains and suggested that a stem of vertical drains to be effective would require a very large number of installations. Since such installations would be expensive, complete dependency upon vertical drainage wells is not recommended. The possibility remains, however, that further experimenting with drainage of this type, possibly by means of holes of larger diameter excavated by means other than those used in water-well drilling, might lead to the development of a satisfactory system. Unfortunately, the depth of 60 to 80 feet required for the deeper drains would make large-diameter installations more than a routine matter.

Although the vertical drains were unsuccessful in tapping the pervious zones, it is evident that the construction of a continuous vertical drainage wall that would cut through all members of the slide would statistically be obliged to intersect

perVIOUS zones in its path. If, for example, a vertical drainage wall could be constructed throughout the full depth of the slide along the centerline of Walomao Road, it is certain that numerous pervious pockets would be encountered and that the influence of the impervious barriers between the pervious zones could be minimized. The construction of a drainage wall to the full depth of the slide does not appear feasible, but it would not be economically prohibitive to construct a continuous drain in a trench with a depth of 20 to 30 ft.

The readings on the piezometers indicate quite clearly that the water levels are highest in the general neighborhood of Walomao Road. Therefore, a drain along this road would have a more beneficial effect than one in any other location possible within the slide. If a drain were installed to a depth of 30 ft below the roadway surface, the water level would, in general, be lowered from 20 to 25 ft. Such a lowering would increase the intergranular stresses at the surface of sliding by at least 100 lbs per sq ft and would substantially increase the shearing resistance of the material. The water could be collected in a conduit with a gravity outlet toward Kipona Place; therefore, pumping would not be required. Construction of such a drain could be carried out in a manner similar to that for the installation for deep sewers and would not involve unusual techniques or equipment. Furthermore, the installation of the drainage system beneath Walomao Road would have the advantage of requiring no trespass beneath property not owned by the City.

The favorable aspects of the trench drain appear in the

ter's estimation to be sufficiently compelling to warrant a full-scale installation. Therefore, such an installation is recommended for favorable consideration. Certain details of construction are outlined in the following section.

In addition to the drainage to be afforded by the Waiomao drainage wall, further attention should be given to the diversion of as much water as possible from the slide. The Engineer's inspection of the floor of the existing quarry indicated that a substantial part of the area is covered by broken rock into which any falling rain could immediately be absorbed. Much of this water unquestionably finds its way into the slide. The measures already taken by the city to intercept water flowing over the edges of the cliffs surrounding the quarry and to conduct it from the slide area are considered the utmost importance and are believed to be among the most effective stabilization measures possible in the area. It is believed, however, that these measures should be supplemented to the greatest possible extent by the reduction of the catchment area of the slide. Investigations should be made regarding the areas that may contribute water to the slide material and to the possibility for providing these areas with impervious pavements or semi-pervious pavements that may permit the diversion of most of the water before it reaches the underground. The history of the slide warrants the statement that attempts should be made to prevent the entrance of all possible water into the sliding mass.

IMAGE TRENCH

A cross section through the proposed drainage trench is

In Fig. 9. Because it is anticipated that many semi-pervious pervious water-bearing pockets will be encountered during excavation, it will be necessary to protect the sides of the trench by sheeting. The sheeting, however, should not be driven in advance, even if this could be done in spite of the presence of boulders, because it is a vital part of the program to determine where seepage takes place and to ascertain the pattern of permeability of the slide in the neighborhood of the drain. Therefore, a system of short vertical lagging or of horizontal sheeting is considered preferable because the character of the materials can then be observed with care.

During the excavation of the trench, a detailed record of the materials encountered in both faces of the trench should be kept by an experienced soils engineer. In addition, notations should be made concerning the quantity of seepage. It is possible that certain extremely pervious zones may be encountered that will have as built-in drainage systems extending under far larger areas than the drainage trench itself. Indeed, it is anticipated and hoped that this will be the case because it is believed that pervious pockets exist within the sliding mass. It is quite possible that the intersection of a pervious network in one or two places by the drainage trench may prove to be the means for draining a very large area of the slide. Careful records are necessary because it may prove advisable to exploit such pockets if they are encountered by supplementary drainage systems, possibly including small drifts or tunnels to follow up the wet zones. The necessity for such work and the effectiveness of carrying it out will be governed by the results of

own in Fig. 9. Because it is anticipated that many semi-pervious pervious water-bearing pockets will be encountered during the excavation, it will be necessary to protect the sides of the trench by sheeting. The sheeting, however, should not be driven in advance, even if this could be done in spite of the presence of boulders, because it is a vital part of the program to determine where seepage takes place and to ascertain the pattern of permeability of the slide in the neighborhood of the drain. Hence, a system of short vertical lagging or of horizontal sheeting is considered preferable because the character of the materials can then be observed with care.

During the excavation of the trench, a detailed record of the materials encountered in both faces of the trench should be kept by an experienced soils engineer. In addition, notations should be made concerning the quantity of seepage. It is possible that certain extremely pervious zones may be encountered that will serve as built-in drainage systems extending under far larger areas than the drainage trench itself. Indeed, it is anticipated and hoped that this will be the case because it is believed that such pervious pockets exist within the sliding mass. It is quite possible that the intersection of a pervious network in one or two places by the drainage trench may prove to be the means for draining a very large area of the slide. Careful records are necessary because it may prove advisable to exploit such pockets if they are encountered by supplementary drainage systems, possibly including small drifts or tunnels to follow up the wet zones. The necessity for such work and the effectiveness of carrying it out will be governed by the results of

merometer observations made during the period of installation of the drains.

The grain size of the backfill material will require careful selection in order to provide for the free inflow of water and at the same time to prevent clogging by the migration of fines. It may be necessary to provide several vertical filter layers becoming progressively coarser toward the center of the drainage blanket. The required grain size cannot be determined in advance but must be developed as the character of the materials adjacent to the drainage trench is learned during the excavation. Thus, the excavation of the trench must be accompanied not only by expert description of the materials encountered, but by grain-size determinations of the various types of deposits in order that the appropriate filter material can be selected. Since it will be undesirable to have large sections of the drain standing open, the requirements for the filter materials will have to be worked out promptly by the resident soils engineer who will then direct that materials should be placed at various locations in the trench. In general the filter requirements can be based on those commonly accepted for the backfill of drainage trenches above perforated pipe, and it is considered likely that sands and gravels used for concrete aggregates will be acceptable for various portions of the filter system. Therefore, the adjustment of grain sizes determined by the character of the materials that may be encountered will not involve delays or unusual hardships to the construction forces. Nevertheless, such an adjustment will be a vital aspect of the drainage installation

and only the most competent inspection should be utilized for control of the work.

Care must be exercised in constructing the trench in order to avoid activating the upper half of the slide. Ample bracing should be provided, and preferably not more than about 50 feet of trench should be open at any one time. The specifications should emphasize that painstaking work must be done and that speed of execution is a very secondary consideration.

Inasmuch as loose sand or gravel is quite compressible, the backfill in the trench will allow excessive movement of the upper half of the slide as the braces are removed unless the backfill is in a dense state. Therefore compaction will be required.

CONCLUSION


The data contained in this report indicates to the writer that the greatest likelihood for stabilization of the Waiomao slide at least expense resides in the installation of a vertical drainage trench to the maximum feasible depth, preferably 30 ft, backfilled with suitable filter materials. The work must be done under the control of an experienced engineer who will observe the character of the soil and its permeability from point to point and will design the appropriate filters accordingly. In addition, steps should be taken to reduce the inflow to the slide area as much as possible.

It cannot be guaranteed that the procedures recommended in this report will result in complete stabilization of the slide. Unfortunately, the writer does not know of any method,


at any cost, that could guarantee stability. He considers, however, that the proposed measures afford a high degree of probability of success. The cost of the proposed measures can be estimated with reasonable accuracy and the authorities of the City and County will then be in a position to judge whether the work may justifiably be undertaken.

KEY PLAN
FIG. 2

1" = 100'
• Piezometer
□ Tiltmeter
△ 10-in. drain
* 12-in. drain



CONDENSED PIEZOMETRIC OBSERVATION
Approx 8+50
FIG. 3



Legend:
 1 Usual piezometric level
 2 Level occasionally exhibited
 Ground surface profiles approximate
 TM Tiltmeter

Approx 10+40

Approx 9+30

Approx 8+50


Elevation - Ft

AVERAGE RATES OF MOVEMENT

APRIL - JUNE 1958

(FEET PER 100 DAYS)

LOCATION	STA.	Lateral	Vertical
KUAHAO ST	B	0.36	0.45 down
	C	0.30	1.10 "
	D	0.68	0.95 "
	E	0.95	0.92 "
			0
WAIOMAO RD	7+89	1.00	0.07 down
	B+56	1.02	0.10 up
	9+27	0.95	0.06 down
	7+20	0.14	0.07 up
	7+59	0.17	0
KIPONO PL	8+28	0.46	0.28 up
	9+49	0.70	0.30 up



SUMMARY OF MOVEMENTS


APRIL - JUNE 1958

FIG. 4

COMPARISON OF HORIZONTAL AND
TRENCH DRAINS
FIG. 8


A, B, C Auger drains 100 ft long
D Drainage trench 25 ft deep
I Observed water levels

~~INSTRUMENTS~~
Rock (3)



Completed Filter
TRENCH DEAN
SKETCH OF


10" ϕ perf. pipe



(Details to depend on ground encountered)

Coarse filter
Fine filter

4' min



30'

